



There is two options how to mount controller:

1. Screw controller down with M5 screw

2. Screw M6 screw from bottom to the controller.

Maximum length of thread witch goes to the controller is 8mm.

MATERIAL:		NAME:	DATE:	
WEIGHT:		DRAWN: Michal Popelka	14.08.2025	
PROJECTION: [ISO E]		CHECKED:		
ACCURACY:		()		
TOLERANCE:				
	NUMBER:	SL_middle_voltage	Size A4	Scale 1:2
	PROJECT:	SL_middle_voltage-rev_1	Rev 1	List 1/1